

TEST REPORT

Page 1 of 23

REPORT NUMBER:

TURR120132554- REVISED I

APPLICANT NAME

Lande End. Met. Ür. San. ve Tic. Ltd. Şti.

ADDRESS

Eskişehir O.S.B. 20. Cad. No:14 Eskişehir TURKEY Attention: Aysun Altınay (aysun.altınay@lande.com.tr)

SAMPLE DESCRIPTION:

Fan Modules (Rack Cabinet Accessories)

DATE IN:

16 November, 2012

DATE OUT:

26 November, 2012 / 27 November, 2012

PRODUCT'S CODE:

See attachment

REQUEST:

RoHS Test was performed on the item.

RESULTS:

See attachment

CONCLUSION:

See attachment

NOTE:

In this revised I report, sample description part and product's code were changed, by the request

of the vendor.

This report replaces the report no TURR120132554 dated on 26 November, 2012 and must be

used instead of it.

The test results relate only to the items tested. The whole and/or the part of this test report shall not be reproduced and shall not be shared with third parties, nor to be used for PR activities without the written permission of INTERTEK Test Hizmetleri A.S.

The reported uncertainty is based on a standard uncertainty multiplied by a coverage factor k=2, providing a level of confidence of approximately 95%. The uncertainty evaluation has been carried out in accordance with ISO/IEC 17025 and UKAS accreditation requirements. Unless otherwise is specified, all Pass or Fail results are given without uncertainty considered. When uncertainty is taken into account, the result may be borderline. Borderline results need to be re-tested to determine their disposition up to customer's decision. Opinions and interpretations expressed herein are outside the scope of UKAS accreditation. Tests marked (*) in this test report are not included in the UKAS accreditation schedule for this laboratory.

Bora Şirinbilek Coordinator Neslihan Sözer Chemical Laboratory Manager



Intertek Test Hizmetleri A.S.

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna 34197 - ISTANBUL / TURKEY
Phone: +90.212, 496 46 46 Fax: +90.212, 452 80 55
e-mail: labtest.turkey@intertek.com
www.intertek-turkey.com





REPORT :TURR120132554 - REVISED I

Page 2 of 23

27 November, 2012

PRODUCT'S CODE:

FAN MODÜLÜ
LA08F1O00U00FSA-BL
LA08F1O00U00FSA-LG
LA08F1O00U00WMA-LG
LA08F1T00U00FSA-BL
LA08F1T00U00FSA-LG
LA08F1T00U00WMA-LG
LA08F2D00U00FSA-BL
LA08F2O00U00FSA-BL
LA08F2O00U00FSA-LG
LA08F2O00U00RMA-BL
LA08F2O00U00WMA-LG
LA08F2T00U00FSA-BL
LA08F2T00U00FSA-LG
LA08F2T00U00RMA-BL
LA08F2T00U00RMA-LG
LA08F2T00U00WMA-LG
LA08F4D00U00FSA-BL
LA08F4O00U00FSA-BL
LA08F4O00U00FSA-LG
LA08F4O00U00RMA-BL
LA08F4O00U00RMA-LG
LA08F4O00U00SRA-BL
LA08F4O00U00SRA-LG
LA08F4T00U00FSA-BL
LA08F4T00U00FSA-LG
LA08F4T00U00RMA-BL
LA08F4T00U00RMA-LG
LA08F4T00U00SRA-BL
LA08F4T00U00SRA-LG
LA08F6O00U00SRA-BL
LA08F6O00U00SRA-LG
LA08F6T00U00SRA-BL

LA08F6T00U00SRA-LG

